



NOTE: HORIZONTAL
UNITS CAN NOT BE
COMPLETELY DRAINED

**SWEEP MODE HORIZONTAL
USING COMPRESSED GAS SOURCE
CONTINUOUS OPERATION**

KEY	
BALL VALVE	
PRESSURE CONTROL VALVE	
FLOW METER	
SAFETY RELIEF VALVE	
BUTTERFLY VALVE	
NEEDLE VALVE	
FILTER	

PI - PRESSURE INDICATOR
TI - TEMPERATURE INDICATOR
PS - PRESSURE SWITCH
PCV - PRESSURE CONTROL VALVE
FI - FLOW INDICATOR